

Probabilistic Life Assessment and Aged Materials Testing for Service Feedback of Gas Turbine Components

Patxi Fernandez-Zelaia¹, Michael Kirka¹, Sebastien Dryepondt¹, Yousub Lee¹, Anand Kulkarni², Kyle Stoodt², Jason Weissman², Andreas Rucki², Santosh Narasimhachary²

¹ Oak Ridge National Laboratory
 ² Siemens Corporation Corporate Technology

ORNL is managed by UT-Battelle, LLC for the US Department of Energy



Unrestricted

Extreme Environment Materials

More challenging component operating conditions:

- Higher operating temperatures /
 pressures
- Cyclic operation
- Wider range of fuels
- Steam

Resulting materials issues:

- Creep
- Fatigue (LCF, HCF, TMF, ..)
- Steamside oxidation / scale
 spallation / erosion
- Fireside corrosion / hot corrosion
- Alloy / coating selection
- Welding/fabrication
- Wear (impact/friction/fretting)

Components:

Combustion plants


- Heat exchangers
 - Superheaters
 - Reheaters
 - Waterwalls
- Gas clean-up systems


Gasification plants

- Heat exchangers
- Ductwork
- Gas clean-up systems

Gas/Steam turbines

- Combustors,
- Turbine components
- (Vanes, Blades)
- Compressors









Common materials challenges exists – need for synergy activities

Aged Materials Data – Incorporated into Design




Open slide master to edit

• Properties in production cast parts have variability and uncertainty that is not typically characterized or considered in design.



Data Generation to establish Process-Structure-Property Correlations

Proposed Blade Sectioning plan



Studies to be extended to Haynes 282 (for A-USC/Gas turbine applications)




Open slide master to edit

Microstructure Characterization

- Characterization work also ongoing at Munich Siemens facility
- Confirm fine recrystallized structure in one blade
- Characterization of root section















Microstructure Characterization

- Microscopy performed on three blades
 - As-fabricated
 - 78khrs cumulative service hours (3 intervals)
 - 33khrs + repair + 33khrs + repair + 12khrs, sent to ORNL
 - 49khrs cumulative service hours
 - pulled, over-aged, dimensionally out of tolerance sent to ORNL
 - Recrystallized microstructure due to HT or service (?)
 - over-aged to make metal easier to repair (lower strength), standard HT to return to service (solution, primary, secondary)




CAK RIDGE 1-5mm grains






~1-5mm grains



33khrs + HT + 33khrs + HT + 12khrs

100-500µmgrainsmaster to edit

Microstructure Characterization – blades






Microstructure Characterization – blades

As-fab

49khr




- Moderate coarsening of gamma-prime
 - Initial 325nm
 - 49khrs + HT 2.35µm
 - 33khrs + HT + 33khrs + 12khrs 2.64µm

Fine scale precipitate tends to coarsen

Eutectic unaffected



Preliminary Creep results (760C 690MPa)



Open slide master to edit

Preliminary Creep results (760C 690MPa)

- Exposure drives an increase in gamma prime size which drives down remaining life
- Repairs occasionally performed impose additional HT cycle
 - Recrystallization either due to service or these repairs
- Smaller grain size results in debit on creep life
- Consistently upper blade exhibits longer life
 - Need to characterize returned samples, perhaps lower temperatures inhibit coarsening...?

